



T-91 Non-Solvent Degreaser



FEATURES

- Ideal for traditional solvent cleaning, plastic basin style part washers, and dip tanks
- Moderate foam for effective mechanical cleaning
- Contains no solvents
- Conforms to VOC regulations in US and Canada
- Zero VOCs: VOC's per CARB/OTC/ LADCO: 0 g/L, VOC content per SCAQMD: 0 g/L
- pH = 6-9

APPLICATIONS

- Basin style parts washer
- Bilges
- Compressors
- Concrete
- Dip Tanks
- Drill presses
- Engines
- Floors
- Forklifts
- Grease traps
- Machinery
- Marine
- Tanks
- Tools
- Walls

SPECIFICATIONS AND APPROVALS

- NSF International A1

PROPERTIES

Appearance/Physical State	Colorless/Liquid
Odor	Characteristic, Slight
Boiling Point/Range	97°C
Vapor Pressure	<0.01 kPa
Flammability Limit	Not Applicable
VOC Content	0%
Flash Point	>93.33°C
Evaporation Rate	>1
Viscosity	<20.5 cSt
Solubility (water)	Miscible

DIRECTIONS

(Trigger) Apply product to surface then agitate with a brush, cloth, or wipe. Remove soils by wiping. Rinse with water for a completely residue-free surface. NOTE: Test for compatibility. Do not heat above 175°F (79°C). Do not allow parts to soak longer than 24 hours.

USE T-91 UNDILUTED (STRAIGHT) AS A DIRECT SOLVENT REPLACEMENT FOR ALL HEAVY DUTY DEGREASING APPLICATIONS. DILUTION RATIO PRODUCT: WATER (AS A NEUTRAL PH CLEANER)

WATER	EQUIPMENT
1:10 - 1:75	FLOORS: Light to Heavy Duty Cleaning/Degreasing
UNDILUTED to 1 : 10	METALS: Heavy Duty Cleaning/Degreasing
1:20 - 1:80	PLASTICS, RUBBERS & PAINTED SURFACES
1:50 - 1:100	GLASS
1:10 - 1:80	PRESSURE WASHING: Light to Heavy-Duty Cleaning/Degreasing
1:1 - 1:25	SOAK TANKS [DO NOT EXCEED 140°F (60°C)]

HANDLING

Safe Handling

- Avoid all personal contact, including inhalation. Wear protective clothing when risk of exposure occurs. Use in a well-ventilated area.
- Prevent concentration in hollows and sumps. DO NOT enter confined spaces until atmosphere has been checked. Avoid smoking, naked lights or ignition sources.
- Avoid contact with incompatible materials. When handling, DO NOT eat, drink or smoke. Keep containers securely sealed when not in use.
- Avoid physical damage to containers. Always wash hands with soap and water after handling. Work clothes should be laundered separately.
- Use good occupational work practice. Observe manufacturer's storage and handling recommendations contained within the SDS. Atmosphere should be regularly checked against established exposure standards to ensure safe working conditions.
- DO NOT allow clothing wet with material to stay in contact with skin. See the SDS for Other Information.

STORAGE

Suitable Container

- Store in original packaging. Check all containers are clearly labeled and free from leaks. No known storage incompatibilities.

DISPOSAL INFORMATION

- Consult State Land Waste Management Authority for disposal. Bury residue in an authorized landfill. Recycle containers if possible or dispose of in an authorized landfill.

AVAILABLE PRODUCTS

Part No.		Net Contents	Container	Case Pack	Case Wt.
US	Canada				
06328	C06328	32 fl oz / 946 mL	Trigger	12	30 lbs
06301	C06301	1 gal / 3.78 L	Bottles	4	38 lbs
06355	C06355	55 gal / 208 L	Drum	1	535 lbs
06330	-	330 gal / 1249 L	Tote	1	2968 lbs



CONTACT YOUR ITW PRO BRANDS REPRESENTATIVE TODAY!

800.241.8334 | www.itwprobrands.com/lps

LPS® is a registered trademark of Illinois Tool Works • All Rights Reserved