

HANDLING

 Protect material from direct sunlight. When using do not smoke. Explosion-proof general and local exhaustventilation. Take precautionary measures against static discharges. All equipment used whenhandling the product must be grounded. Use non-sparking tools and explosion-proof equipment. Avoid contact with eyes. Avoid prolonged exposure. Wear appropriate personal protective equipment. Observe good industrial hygiene practices.

STORAGE

• Store locked up. Keep away from heat, sparks and open flame. Prevent electrostatic charge build-up by using common bonding and grounding techniques. Store in a cool, dry place out o fdirect sunlight. Store in tightly closed container. Store in a well-ventilated place. Keep in an areaequipped with sprinklers. Store away from incompatible materials (see Section 10 of the SDS).



DISPOSAL

 Collect and reclaim or dispose in sealed containers at licensed waste disposal site. Incinerate thematerial under controlled conditions in an approved incinerator. Do not incinerate sealedcontainers. If discarded, this product is considered a RCRA ignitable waste, DO01. Dispose of contents/container in accordance with local/regional/national/international regulations

FEATURES

- Tamper Proof Torque Mark
- Safe for most surfaces
- Highly visible
- Excellent adhesion
- Visually detects loose nuts & bolts
- Provides warranty protection
- Marks fluoresce under black/UV light.

PHYSICAL PROPERTIES

Physical State	Liquid.	
Odor	mild	
Flash Point	23.0 °F (-5.0 °C) Tag Closed Cup	
Boiling Point	175 °F (79.44 °C)	
VOC Content	42.28%, 430 g/L	
Vapor Density	> 1	
Prop 65 Warning	YES	

AVAILABLE IN

Container Type	Units/Case	Color	Part #
1 oz.	24	Orange	83514



CONTACT YOUR ITW PRO BRANDS REPRESENTATIVE TODAY!

800.241.8334 | www.itwprobrands.com