

Hi-Spot Blue

HANDLING

 Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Avoid prolonged exposure. Should be handled in closed systems, if possible. Provide adequate ventilation. Wear appropriate personal protecti

STORAGE

Store locked up. Store in original tightly closed container.
Store away from incompatible materials (see Section 10 of the SDS).

DISPOSAL INFORMATION

 Dispose of contents/container in accordance with local/regional/national/international regulations.

FEATURES

- Detects high spots on bearings, gears and other close fits
- Blue, soft, uniform paste spreads easily and evenly
- · Never dries out
- Film remains pliable and transferable for months
- Saves time and money in surface scraping work



PHYSICAL PROPERTIES

Physical State	Liquid.	
Odor	Slight petroleum odor.	
Flash Point	> 200.0 °F (> 93.3 °C)	
VOC Content	0	
Evaporation Rate	< 1 (BuAc = 1)	
Vapor Density	> 1 (air = 1)	
Prop 65 Warning	YES	

AVAILABLE IN

Container Type	Units/Case	Color	Part #
.55 oz tube	36	blue	83307

