

**STORAGE**

- Keep away from open flames, hot surfaces and sources of ignition. Keep containers tightly closed in a cool, well-ventilated place. Keep out of the reach of children. Keep container closed when not in use. Keep away from incompatible materials.

**HANDLING**

- Avoid contact with skin, eyes and clothing. Keep away from open flames, hot surfaces and sources of ignition. Take precautionary measures against static discharges. Use only in an area containing flame proof equipment. Ensure adequate ventilation.

**DISPOSAL**

- Dispose of contents/container to an approved waste disposal plan

**FEATURES**

- Applies clear mark barely detectable to the eye
- Excellent for security applications
- Marks on plastic, glass and nonporous surfaces
- Drying Time: 45 seconds to 1 minute

**PHYSICAL PROPERTIES**

<b>Appearance / Physical State</b>	Liquid.
<b>Color</b>	Clear.
<b>Odor</b>	Aromatic
<b>Flash Point</b>	108.0 °F (42.2 °C)
<b>Boiling Point / Range</b>	318 - 338 °F (158.89 - 170 °C)
<b>VOC Content</b>	90% ; 809 g/L
<b>Evaporation Rate</b>	< 1 (BuAc = 1)
<b>Vapor Density</b>	> 1 (air = 1)
<b>Prop 65 Warning</b>	YES

**AVAILABLE IN**

Color	Units/Case	Marker Tip	Net Contents	Part #
clear	48	medium, felt (#29)		91195
Clear	4		1 gal	82195